
Nine Springs Valley Interceptor – Mineral Point Extension: Pipe Investigation Update

Commission Meeting March 13, 2025

Agenda


Location Map



Work completed

- Cleaning of pipe, intense cleaning at sags (daily)
- Dewatering of pipe, at sags and endpoints (daily)
- Grouting of multiple joints, 11 joints repaired
- >1250 Gallons of Polyacrylamide grout
- 60 tubes of Polyurethane grout
- Reduced (stopped) the infiltration of groundwater & soil
- Stabilized the soil / foundation of the pipe
- By-pass pumping system removed

Video - O/S Joint 300-ft



Video: Offset Joint during repair



- Video to display the I/I
 - > Water
 - Material

Video: Joint showing material infiltration

Photos – O/S Joint 300-ft During Repair







Key Notes:


- I/I rate
- Water level

Repair Photos – O/S Joint 300-ft after repair



Photos – O/S Joint 284-ft – During Repair






Key Notes:

- Decreased water level
- No water movement

Photos – O/S Joint 284-ft after repair



Repair Photos – Other joints after repair



Key Notes:

- Water level
- See bottom pipe



Why Not CIPP

- Goal was to stabilize the pipe
- Grouting of joints was sufficient to reduce (stop) infiltration of groundwater & soil
- Any pipe deficiencies (joints or cracks) leaking were addressed
- Worst areas The sags were addressed requiring the most effort
- Entry occurred during the repair allowing upfront inspection/information gathering as compared to any previous camera inspection

Next Steps

- Restore site
- Finalize costs
- Replace pipe as part of Nine Springs Valley Interceptor Phase 2
 - ➤ Schedule: Design 2025, Construction 2026

Questions?

Madison Metropolitan
Sewerage District

Madison Metropolitan Sewerage District